Aeroprakt Ltd	
---------------	--

# AEROPRAKT SERVICE BULLETIN

# No. SB A32-19

# AMENDMENT TO PILOT OPERATING HANDBOOK OF A32 AND A32L AIRPLANES

# **Repeating symbols:**

Please, pay attention to the following symbols throughout this document marking important information.

▲ WARNING: Identifies an instruction, which if not followed may cause serious injury or even death.

• **CAUTION:** Denotes an instruction, which if not followed, may cause severe damage.

• **NOTE:** Information useful for better handling.

Release date: 03.01.2024

Effective date: 03.01.2024

Completion date:

Superseded notice: none

Model: A32 and A32L Serial number(s) affected: A32 aircraft S/N – see next page and A32L aircraft S/N 2-5, 25-28

## AEROPRAKT

### SERVICE BULLETIN

## No. SB A32-19

#### 1) Planning information

#### 1.1) Aircraft affected

A32 aircraft serial No. 2-71, 73-75, 78, 79, 82, 83, 85, 87, 91, 93, 94, 96, 97, 102, 109, 110, 111, 115, 116, 118, 119, 120, 123, 125-128, 130, 131, 140, 143-148, 153-155, 157, 163, 164, 168, 169, 171, 179, 182, 183, 185, 186, 190 193, 195-200, 203, 205, 207, 208, 211, 216, 217, 221-223, 229, 232, 234, 240, 243, 244, 249, 250, 252 255, 257 259, 261, 264, 265, 267, 269, 270, 273 276, 278, 279, 281 283, 285, 287 289, 292 300, 303 307, 309, 312 and A32L aircraft serial No. 2-5, 25-28.

#### 1.2) Reason

Clarification of wording.

#### 1.3) Subject

The section **AFHT antiservo/trim tab control system** of the **Pilot Operating Handbook** (POH) of the above listed A32 and A32L aircraft.

#### 1.4) Compliance

The POH of all other A32 and A32L aircraft are compliant with this service bulletin.

#### 1.5) Approval

The technical content of this service bulletin has been approved by Aeroprakt.

#### 1.6) Manpower

Estimated man-hours: 5 minutes.

#### 1.7) Mass data

Mass change - none.

#### 1.8) Revision of other documents

None

#### 1.9) Spare parts

None

#### 2) Spare parts information

None

#### 3) Accomplishment / Instructions

**3.1**) In the POH of the above listed A32 and A32L aircraft, section **AFHT antiservo/trim tab control system,** correct the last sentence to read as follows:

The antiservo/trim tab angles of deflection are: upward 7.4±1°, downward 1.6±1° when the AFHT is in its neutral position.